

Multilin 8 Series Protection and Control Relay Platform

Firmware Version 2.45

Release Notes

GE Publication Number: GER-4880
Copyright © 2020 GE Multilin

Overview

Summary

GE Grid Solutions releases 8 Series firmware version 2.45 for Multilin 8 Series Protection Relays.

Highlights of this release include the following:

Multilin 8 Series firmware version 2.45

- **Platform**
 - Fault Locator Logical Node attributes refreshed
 - IEC 61850 GOOSE Configuration Revision resolved
 - Applied Security patch on VxWorks

- **869**
 - Learned Data Recorder and Power Quality Event files corrected
 - Single Phase Trip Logic enhanced

Release Date: **Feb 20, 2020**

Multilin 8 Series firmware versions 1.2x and below cannot be upgraded to firmware version 2.45. Please contact us to upgrade the product.

Upgrade the firmware to version 2.45 by downloading the file directly from our website:

[850 Feeder Protection System](#)

The latest EnerVista 8 Series Setup software is available at the same location. The software supports Windows 7, 8.1, and 10.

Please contact your local Multilin sales representative or Multilin Customer Service Department for any questions regarding this upgrade.

Release details

In the following release descriptions, a revision category letter is placed to the left of the description. See the Appendix at the end of this document for a description of the categories displayed.

Firmware version 2.45

Platform

C **Fault Locator Logical Node attributes refreshed**

Corrected refresh functionality on Fault Locator Logical Node attributes (RFLO).

C **IEC 61850 GOOSE Configuration Revision resolved**

The GOOSE configuration file was one revision ahead of the CID file. This is resolved to match.

E **Applied Security patch on VxWorks**

Applied a Wind River VxWorks security patch.

869

R **Learned Data Recorder and Power Quality Event files corrected**

LDR and PQE files were unintentionally removed from firmware version 2.43. As of version 2.45, they are restored.

E **Single Phasing Trip Logic enhanced**

Single phasing trip logic is enhanced to track on RMS Current Magnitude Values to improve element accuracy.

Appendix

Change categories

This document uses the following categories to classify the changes.

Table 1: Revision Categories

Code	Category	Comments
N	New feature	A separate feature added to the relay. Changes to existing features even if they significantly expand the functionality are not in this category
G	Change	A neutral change that does not bring any new value and is not correcting any known problem
E	Enhancement	Modification of an existing feature bringing extra value to the application
D	Changed, incomplete or false faceplate indications	Changes to, or problems with text messages, LEDs and user pushbuttons
R	Changed, incomplete or false relay records	Changes to, or problems with relay records (oscillography, demand, fault reports, etc.)
C	Protocols and communications	Changes to, or problems with protocols or communication features
M	Metering	Metering out of specification or other metering problems
P	Protection out of specification	Protection operates correctly but does not meet published specifications (example: delayed trip)
U	Unavailability of protection	Protection not available in a self-demonstrating way so that corrective actions could be taken immediately
H	Hidden failure to trip	Protection may not operate when it should
F	False trip	Protection may operate when it should not
B	Unexpected restart	Relay restarts unexpectedly

For further assistance

For product support, contact the information and call center as follows:

GE Grid Solutions

650 Markland Street

Markham, Ontario

Canada L6C 0M1

Worldwide telephone: +1 905 927 7070

Europe/Middle East/Africa telephone: +34 94 485 88 54

North America toll-free: 1 800 547 8629

Fax: +1 905 927 5098

Worldwide e-mail: multilin.tech@ge.com

Europe e-mail: multilin.tech.euro@ge.com

Website: <http://www.gegridsolutions.com/multilin/>