

# FMC-T6 Overhead Line Sensor

## Firmware Version 22

### Release Notes

GE Publication Number: GER-4698

Copyright © 2015 GE Multilin

## Overview

---

### Summary

GE Digital Energy releases Firmware version 22 for the FMC-T6 Overhead Line Sensor. This firmware is specific to the FMC-T6-X-X-X and affects to SNG-Sensor Network Gateway. Both devices belong to Intelligent Line Monitoring System. Highlights of this release include the following:

#### FMC-T6 Overhead Line Sensor:

- Modification of radio output configuration
- Averaging Algorithm modified for all DC analog channels.
- Sampling frequency increased.
- New default value set to cycle count parameter.

#### FMC-T6 firmware compatibilities:

### WARNING

- Firmware version of SNG3-X-X-X-X models (SNG-Sensor Network Gateway), which are linked to the FMC-T6-X-X-X that will be updated to the released firmware, must be upgraded to the following firmware versions:
  - SNG-3-X-X-X DSP firmware:
    - Version 15 (Built date: July, 28<sup>th</sup> 2014) or above
  - SNG-3-X-X-X Main firmware:
    - Version 48 (Built date: March, 27<sup>th</sup> 2015) or above

### WARNING

#### UPGRADING FIRMWARE PROCEDURE:

- Firmware upgrading process for the complete ILMS must be performed by following the next steps in the order listed below.

When FMC-T6-X-X-X firmware version is 15 or below:

1. Upgrade SNG-3-X-X-X Main firmware to version 48.

2. Upgrade FMC-T6-X-X-X firmware to version 22.
  3. Check in ILMS server that communication with sensors has been lost before going to the next step.
  4. Upgrade SNG-3-X-X-X DSP firmware to version 15.
- Instructions, that are described in the document **GET-20032-ILMSUpgradingFirmware**, must be followed to upgrade the firmware

Release Date: May, 12<sup>th</sup> 2015

NOTE: Upgrading from a previous version of the FMC-T6 firmware to the new 22 firmware version can be done remotely via ILMS server application.

NOTE: Bootcode will be upgraded automatically when firmware is updated from firmware version equal or below 15

**Please contact your local GE sales representative or Customer Service Department (CST) for any questions regarding this upgrade.**

## Release details

---

In the following release descriptions, a revision category letter is placed to the left of the description. Refer to the Appendix at the end of this document for a description of the categories displayed.

### FMC-T6 Overhead Line Sensor - Firmware version 22 Release Details:

#### **C Modification of radio output configuration**

Radio configuration modified and default value updated to be compliance with new standard EN 300 328 v.1.8.1.

Firmware version of SNG2-0 model (SNG-Sensor Network Gateway), which is linked to the FMC-T6-X-2-X models that will be updated to the released firmware, must be upgraded to the following firmware versions to be compliance with new standard EN 300 328 v.1.8.1.

- SNG2-0 Main firmware:
  - Version 6

Instructions, that are described in the document GET-20032-ILMSUpgradingFirmware, must be followed to upgrade the firmware.

#### **M Averaging Algorithm modified for all DC analog channels.**

Increased the number of samples used during Moving Average Filter calculation.

#### **M Sampling frequency increased.**

Sampling frequency has been redefined providing greater reliability for filtering 50Hz interferences.

#### **E New default value set to cycle count parameter.**

Minimum value defined to trigger and release an event. Value set to 3 cycles in case of communicating with SNG3 devices.

## Appendix

### Change categories

This document uses the following categories to classify the changes.

**Table 1: Revision categories**

Code	Category	Comments
N	New feature	A separate feature added to the relay. Changes to existing features even if they significantly expand the functionality are not in this category
G	Change	A neutral change that does not bring any new value and is not correcting any known problem
E	Enhancement	Modification of an existing feature bringing extra value to the application
D	Changed, incomplete or false faceplate indications	Changes to, or problems with text messages, LEDs and user pushbuttons
R	Changed, incomplete or false relay records	Changes to, or problems with relay records (oscillography, demand, fault reports, etc.)
C	Protocols and communications	Changes to, or problems with protocols or communication features
M	Metering	Metering out of specification or other metering problems
P	Protection out of specification	Protection operates correctly but does not meet published specifications (example: delayed trip)
U	Unavailability of protection	Protection not available in a self-demonstrating way so that corrective actions could be taken immediately
H	Hidden failure to trip	Protection may not operate when it should
F	False trip	Protection may operate when it should not
B	Unexpected restart	Relay restarts unexpectedly

The revision category letter is placed to the left of the change description.

### Multilin technical support

GE Digital Energy - Multilin contact information and call center for product support is shown below:

GE Digital Energy  
650 Markland Street  
Markham, Ontario  
Canada L6C 0M1

Telephone: 905-927-6222 or 1-800-547-8629 (North America), +34 94 485 88 00 (Europe)  
Fax: 905-201-2098 (North America), +34 94 485 88 45 (Europe)

E-mail: [multilin.tech@ge.com](mailto:multilin.tech@ge.com)

Home Page: <http://www.ge.digitalenergy.com/multilin/>