



Firmware/Software Release Note

Date: **October 2025**Distribution: **Public**Reference: **P14x-RN-EN-91I-1**

MiCOM P40 Agile P14x

Firmware Version 91, Minor Version I

Overview

- This document contains the release notes for Firmware Version 91I for MiCOM P40 Feeder Relay
- Applicable to products: P141, P142, P143 and P145
- Firmware Version 91I is a minor release that succeeds Firmware Version 91H
- Firmware Version 91I supports both Edition 2 and Edition 1 of IEC 61850 (selectable)

Key Updates

- Supports hardware options (7th digit of order code) U, W, and Y in addition to existing R, S and T
- Combine 2 instances SNMP services into one
- New LCCH logical node for IEC 61850 Ed.1 and Ed.2 data models for link status of Ethernet ports (NP2A and NP2B)
- Addition of two DDBs to show link status of NP2A and NP2B ports
- Configuration of HSR/PRP/RSTP/Failover via IED Configurator tool (MCL file)
- Rebranding of ICD template to GE Vernova
- Bug fixes of platform issues
- Ethernet traffic overload protection to handle DDoS attack

Scope of the Release

The scope of this release covers models and protocols as indicated in the table below:

Model	Protocol							
	Courier (1)	Modbus (2)	IEC 60870-5-103 (3)	DNP3 (4)	UCA2 (5)	IEC 61850 (6)	IEC 61850 + 103 (7)	DNP3OE (8)
P141	☐	☐	☐	☐	☐	☒	☒	☐
P142	☐	☐	☐	☐	☐	☒	☒	☐
P143	☐	☐	☐	☐	☐	☒	☒	☐
P145	☐	☐	☐	☐	☐	☒	☒	☐



Key bug fixes in this firmware version

Code	Change ID	Description	Effect
C	PX40PL-513	IEC 61850: Incorrectly formed packet reply from P40 IEDs in rare circumstances	One of the IEC 61850 Clients occasionally loses the connection with P40 IED. This occurs occasionally after a control action from the client.
C	PX40PL-542	The configuration of VIP8 and VIP9 defined in model as Ind08/Ind09 are ignored after renumbering of Logical Node data objects to use 01,02...09 numbering as required for conformance	IEC 61850 client system can have incorrect status information for the affected signals. The affected attributes are Virtual Inputs 8 and 9.
C	PX40PL-558	IEC 61850 Interoperability issue with clients with MMS 'proposedVersionNumber' = 2	The client will not initiate IEC 61850 connection.
R	PX40PL-571	Incorrect display of Primary values as Secondary values in some COMTRADE viewer software tools, whereas the values actually stored are in Primary	Use sees incorrect display of Primary values as Secondary values in some COMTRADE viewer software tools.
C	PX40PL-582	IEC 61850 IED does not respond for 'SetDataValues' request on 'setSrcRef' read only Data Attribute	IED should give a negative response with data access error "object-access-denied" but it does not respond.
C	PX40PL-586	Frequency setting range incorrectly limited to 50Hz only	60Hz setting not selectable.
C	PX40PL-589	Some data changes are not reported via IEC 61850 if 'BufTm' is set > 0	IEC 61850 client system may not receive some data changes.
C	PX40PL-590	IEC 61850: When IED is in 'Test Blocked' mode, SBO 'Cancel' request incorrectly sends negative response	For a control object whose control mode is "SBOs" or "SBOes", after sending 'Select' followed by 'Cancel', then IED sends negative response instead of positive response. User cannot select new command until the timer expires.
C	PX40PL-597	When the Disturbance Record format was extended to contain scaling information, it rendered the memory calculation for IEC 61850 files incorrect	When extraction of DR file is attempted the IEC 61850 ethernet card application will fail. Failure will occur only fail if the number of channels is increased past the default number already configured.
C	PX40PL-602	IEC 61850: IED can incorrectly switch to duplicate GOOSE for some stNum	Subscriber IED can incorrectly switch to duplicate GOOSE message (that is not marked as Simulated). Unlikely to occur intentionally, but maybe by operator error or maliciously. Similarly, when the duplicate GOOSE publishing was stopped, the subscriber IED incorrectly does not immediately switch back to the process GOOSE.

Code	Change ID	Description	Effect
C	PX40PL-612	IEC 61850 Reporting stops after few Select Before Operate control operations	IEC 61850 reporting to client system stops. Client not getting updates reflecting site statuses. Only occurs for SBO commands. Requires restarting (power cycle) of IED to recover.
C	PX40PL-623	IEC 61850: IED loses client communication when EntryID/Buffer Overflow is selected for Unbuffered RCB	The client communication will stop. Need to reconfigure and resend MCL to resolve.
C	PX40PL-626	GOOSE Control Block (GCB) enable and CSWI controls are failing when initiated only from "UniGrid" conformance test tool	No impact to customer, as customer Client systems do not use the specific "UniGrid" encoding. This will only be observed during testing with the "UniGrid" IEC 61850 conformance test tool, resulting to control blocks not initiated.
C	PX40PL-636	IEC 61850: In some rare specific cases of frequent commands, IED may intermittently lose client communication	IEC 61850 Client intermittently loses the client communication.
C	PX40PL-638	Occasional ping loss on the Ethernet port	With an established IEC 61850 connection, if the user successively pings the IED, occasionally there might be no reply to a ping, but there is no direct impact to the IEC 61850 communication.
R	PX40PL-689	COMTRADE Format for IEC 61850 incorrectly shows "1997" instead of "1999"	Some IEC 61850 clients may not decode the COMTRADE file.
C	PX40PL-690	IEC 61850 client read of some whole Logical Nodes may fail in firmware version 91 with multi-client support	Some IEC 61850 clients cannot establish communication with IED.
C	PX40PL-693	IEC 61850 Edition 2 conformance test: Association 'servicesSupportedCalled' shall not contain 'obtainFile'	Non-conformance to Edition 2.0 Test Procedures.
C	PX40PL-694	IEC 61850 Edition 2 conformance test: IED should not send 'CommandTermination-' when the operation is successful	Non-conformance to Edition 2.0 Test Procedures.
C	PX40PL-695	IEC 61850: Control is successful when the IED is in On Mode and the Control has Test flag set, but should fail	Non-conformance to Edition 2.0 Test Procedures. Could affect customer during commissioning/maintenance testing (control unexpectedly actioned).
C	PX40PL-705	IEC 61850 Ed2.0: for a non-configured BRCB, ResvTms is 0 instead of >0	Non-conformance to Edition 2.0 Test Procedures.
C	PX40PL-707	IEC 61850: IED requires the test flag to be present when LLN0.Mod is in Test for LPHD.Sim to be active - not compliant with Tissue 1819	Test flag should be ignored when LLN0.Mod is in Test. Non-conforming to Tissue 1819.

Code	Change ID	Description	Effect
C	PX40PL-708	IEC 61850 Commands incorrectly do not work when the device is in Test/Blocked Mode	User cannot send commands when IED is in Test/Blocked Mode, not compliant with the standard.
C	PX40PL-717	IRIG-B Status changes to 'Card Failed' from 'Signal Healthy' after a long duration of operation	IRIG-B Status changes to 'Card Failed' and loses sync to IRIG-B.
C	PX40PL-725	Frequent logging of short-duration 'SNTP Failure' Alarms	SNTP Sync lost for 5 to 10 seconds and events file will fill with 'SNTP Failure' alarms.
C	PX40PL-726	v91 NIC No Response and NIC MemAlloc Fail Alarms - If dataset contains CF elements	IEC 61850 Client communication and GOOSE are interrupted while ethernet board re-starts due to the NIC alarms.
C	PX40PL-735	v91 NIC No Response Alarms with no CF in data sets	IEC 61850 Client communication and GOOSE are interrupted while ethernet board re-starts due to the NIC alarms.
C	PX40PL-744	If BRCB is configured with a dataset containing SI Unit Data Attribute, IEC 61850 client connection is lost	IEC 61850 client connection is lost if BRCB is configured with a dataset having SI Unit Data Attribute and enabled.
C	PX40PL-823	P40 IEDs with summertime enabled continue sending of IEC 103 telegrams in wintertime	P40 IEDs with summertime enabled continue sending of IEC 103 telegrams in wintertime, although the DST has been enabled, so DCS/SCADA shows wrong time (shifted by 60 minutes).

Hardware Compatibility

Firmware 91I runs on Hardware Suffix P.

Issues Affecting Customer Upgrade/Backwards Compatibility

- Any previous 91 minor version of P14x relays supports hardware options R, S, T. 91I firmware is created to support hardware options R, S, T and the newly introduced U, W, Y.
- To update existing 91 relays from R, S, T hardware option to any of the U, W, Y, the Ethernet board hardware needs to be replaced, and the device firmware needs to be updated for the relays using D&C version 4.1 or later version.
- Concerning backward compatibility of Firmware Version 91I with previous Firmware Version.

S1 Data Models		
	New/Updated	Backwards Compatible
Setting	Yes	No
DNP3	No	Yes
PSL	Yes	No
Language	Yes	No
ICD	Yes	No

S1 Data Models

	New/Updated	Backwards Compatible
RDF	No	Yes
DBF	Yes	No
Cell List	No	Yes

Support Software Compatibility

Requires MiCOM S1 Agile Version 3.2 (or later).

Categories

This document uses the following categories to classify changes:

Code	Category	Description
N	New feature	A separate feature added to the relay. Changes to existing features even if they significantly expand the functionality are not in this category.
G	Change	A neutral change that does not add new value and is not correcting any known problem.
E	Enhancement	Modification of an existing feature bringing extra value to the application.
D	Changed, incomplete, or false faceplate indications	Changes to, or problems with text messages, LEDs, and user pushbuttons.
R	Changed, incomplete, or false relay records	Changes to, or problems with relay records (oscillography, demand, fault reports, and so on).
C	Protocols and communications	Changes to, or problems with protocols or communication features.
M	Metering	Metering out of specification or other metering problems.
P	Protection out of specification	Protection operates correctly but does not meet published specifications (example: delayed trip).
U	Unavailability of protection	Protection not available in a self-demonstrating way so that corrective actions can be taken immediately.
H	Hidden failure to trip	Protection does not operate when appropriate.
F	False trip	Protection operates when it is not appropriate.
B	Unexpected restart	Relay restarts unexpectedly.

For Further Assistance

For questions or further product support, please contact the GE Vernova support teams using:

Region	E-mail	Telephone
Global Contact Centre	GA.support@gevernova.com	+44 1785 250070
Central, East Asia, Pacific	GA.supportCEAP@gevernova.com	+65 6749 0777
India	GA.supportIND@gevernova.com	N/A
Middle East, North Africa, Turkey	GA.supportMENAT@gevernova.com	+971 4 375 6950
Europe, Russia, CIS, Sub-Saharan Africa	GA.supportERCIS@gevernova.com	+34 94 4858854
North America	GA.supportNAM@gevernova.com	+1-877-605-6777 (Global toll-free) +1-800-547-8629 (NAM toll-free) +1-678-844-6777 (Direct)
Latin America	GA.supportLAM@gevernova.com	+55 48 2108 0300