



**GE VERNOVA**

## **Multilin Agile Protection and Control Relay Platform**

### **Multilin Agile Firmware Version 08D**

#### **Release Notes**

GE Vernova Publication Number: GER-5006

Copyright © 2025 GE Vernova

Publication Date: Sept 2025

# Summary

GE Vernova releases the Multilin Agile Firmware Version 08D for the Multilin Agile Protection & Control Relays.

## Multilin Agile Firmware Version 08D

### Release Date: September 12, 2025

- Firmware v08D is compatible with v08C, v08B, v06B, v06A, v05C, v05B, v05A.
- When updating the firmware, files are overwritten, and all settings could be lost.
- Always save the setpoint file before upgrading.
- Configuration of the CID file is required to be created or converted from the previous version using, D&I EnerVista Setup v4.15 or newer
- The latest D&I EnerVista Setup software is available at the same location. The software supports Windows 7, 8.1, 10 and 11.

Note: Please contact your local Multilin sales representative or Multilin Customer Service Department for any questions regarding this upgrade.

# Table of Contents

1	Firmware v08D .....	4
1.1	High PRP traffic .....	4
1.2	FlexLogic Timers .....	4
1.3	Phase rotation ABC/ACB .....	4
1.4	GOOSE Reception mapping to Remote Inputs.....	4
2	Firmware v08C .....	5
2.1	Relay freezes.....	5
2.2	Relay reboots.....	5
3	Firmware v08B .....	6
3.1	Cybersecurity.....	6
3.2	IEC61850 Control Authority .....	6
3.3	Trip Bus Supervision.....	6
3.4	HiZ – High Impedence .....	6
3.5	Motor Protection & Control.....	6
3.6	German and Polish.....	6
3.7	Enhancements to FlexLogic.....	6
3.8	Pos Seq UV 1 and Pos Seq UV 2.....	6
3.9	Ethernet 1 link alarm .....	6
3.10	Neutral Current .....	7
3.11	Breaker Failure .....	7
3.12	Breaker Status .....	7
3.13	Power Demand .....	7
3.14	Default Screens .....	7
3.15	Sensitive Earth Fault.....	7
3.16	Phase – Time over current.....	7
	For Further Assistance .....	8

# 1      **Firmware v08D**

## 1.1      **High PRP traffic**

Section:                      Communication

Impact to customer:      In networks with significant PRP traffic from multiple protection relays, a Multilin Agile device may experience an unexpected reboot

Products Affected:      Multilin Agile

What changed?              Modification in the driver file implemented a node message index check to ensure it will not go out of range and cause a processor to restart

## 1.2      **FlexLogic Timers**

Section:                      Protection

Impact to customer:      In previous versions setting changes made to individual FlexLogic Timers do not take effect until relay was power cycled. This has now been corrected.

Products Affected:      Multilin Agile

What changed?              FlexLogic pickup and dropout settings corrected to take effect without the need to power cycle the relay.

## 1.3      **Phase rotation ABC/ACB**

Section:                      Protection

Impact to customer:      In previous version Phase Rotation setting defaulted to ABC on power cycle when programmed for ACB.

Products Affected:      Multilin Agile

What changed?              Corrected Phase Rotation setting issue where the ACB rotation would only be used till a power cycle was executed. The setting would remain ACB, but internally relay used ABC rotation for calculations resulting in incorrect Sequence component measurements (Ex: Negative Sequence).

## 1.4      **GOOSE Reception mapping to Remote Inputs**

Section:                      Communication

Impact to customer:      The mapping of GOOSE Reception into Remote Inputs was not sequential

Products Affected:      Multilin Agile

What changed?              Mapping has been corrected.

## **2        Firmware v08C**

### **2.1       Relay freezes**

Fixed an issue that caused 20TE models to freeze when a setting was changed through the front panel while the security bypass was activated.

### **2.2       Relay reboots**

Fixed an issue that made the device reboot when sending a configuration that took too long to load.

## **3        Firmware v08B**

### **3.1        Cybersecurity**

Advanced cybersecurity options complying with NERC-CIP/IEC 62351 standards supported.

### **3.2        IEC61850 Control Authority**

IEC61850-control authority feature - OrCAT- Local/remote control feature (described in IEC 61850 7-4: Annex B).

### **3.3        Trip Bus Supervision**

Support added for Trip Bus supervision functionality

### **3.4        HiZ – High Impedence**

Support added for HiZ downed conductor function.

### **3.5        Motor Protection & Control**

Support added for new ordering code options for Motor protection and control.

### **3.6        German and Polish.**

German and Polish languages are now supported

### **3.7        Enhancements to FlexLogic**

Enhancements to FlexLogic as follows,

- Number of Virtual Outputs increased from 128 to 256.
- Number of Virtual Inputs increased from 128 to 256.
- Number of FlexLogic Timers increased from 32 to 64.
- Number of FlexElements increased from 8 to 16.

### **3.8        Pos Seq UV 1 and Pos Seq UV 2**

Fixed an issue that caused Pos Seq UV 1 and Pos Seq UV 2 texts to be displayed incorrectly in drop-down lists.

### **3.9        Ethernet 1 link alarm**

Fixed an issue that prevented Eth 1 link status error alarm from being reset when Eth 1 was enabled.

### **3.10 Neutral Current**

Resolved an issue that prevented the IN calculation from being performed correctly when no current was present in Phase A..

### **3.11 Breaker Failure**

Resolved an issue that caused the Breaker Failure operation and re-trip indication to be unavailable in the Last Trip record and on the HMI.

### **3.12 Breaker Status**

Resolved an issue that caused the breaker status operand 'CB Not Configured' to be unavailable in the Target Messages and FlexOperand list.

### **3.13 Power Demand**

Resolved an issue that caused incorrect Minimum Power Demand calculations when the device was powered off, also addressed a condition where Minimum Power Demand calculation was not blocked when the injected current was less than  $0.02 \times CT$ .

### **3.14 Default Screens**

Resolved issue that prevented Default Screens\Display Time setting from displaying in 20TE.

### **3.15 Sensitive Earth Fault**

Resolved issue that caused SEF IOC to drop out at  $0.5 \times CT$  outside the defined range.

### **3.16 Phase – Time over current**

Resolved an issue that caused the PTOC element to operate incorrectly when a User Curve configured as FR ST Inverse was used

## For Further Assistance

For questions or further product support, please contact the GE Vernova support team

Region	E-mail	Comments
Global Contact Centre	ga.support@gevernova.com	+44 1785 250070
Central and East Asia and Pacific	ga.supportCEAP@gevernova.com	+61 414 730 964
India	ga.supportIND@gevernova.com	+91 44 22648000
Middle East, North Africa and Turkey	ga.supportMENAT@gevernova.com	+971 42929467
Europe, Russia, CIS and Sub-Saharan Africa	ga.supportERCIS@gevernova.com	+34 94 4858854
North America	ga.supportNAM@gevernova.com	+1 877 605 6777
Latin America	ga.supportLAM@gevernova.com	+55 11 36187308