GE

Grid Solutions

EPM Meters

GE Communicator v5.00.0277

Release Notes

GE Publication Number: GER-4957 Copyright © 2024 GE Multilin

Overview

Summary

GE Multilin has released an update to GE Communicator v5.00.0277 which introduces the following features and enhancements:

- Features/Enhancements
 - Updates to support meter enhancements EPM 7000P E1 Ethernet Enhancement
- Bug Fixes
- o Various EPM Meter configuration/visualization fixes

Release Date: January 31, 2024

Release Details

Enhancements

In the following enhancement descriptions, a revision category letter is placed to the left of the description. Refer to the Appendix at the end of this document for a description of the categories displayed.

N Updates to support meter enhancements – EPM 7000P – E1 Ethernet Enhancement

 EPM7000P: Added support for updated E1 Ethernet Card – Network Card Status window -IPv6 address value/configuration

Bug Fixes

EPM7000:

- Fixed issue with Programmable settings editor supporting Software options
- Fixed issue with Manual Export COMTRADE under Log Viewer to generate COMTRADE files.

EPM7000P

- Fixed Partial log retrieval: showing current month's data
- Update to missing V C-A label in DNP>ANALOG INPUT>THD>VCN
- Update to resolve observed error upon connecting to meter "Failed to init security COM [429]
- Fixed unable to connect to meter when the Enable IPv6 option is checked under View > Options.
- Fix to resolve EPM7000P THD logs missing in the Profile
- Update to resolve TOU monitored data set are missing Energy channels.

• EPM9700:

- Update to resolve observed error upon connecting to meter "Failed to init security COM [429]
- Fix for PQDIF file generation to support Harmonic group or Harmonic sub groups

R	Changed, incomplete or false relay records	Changes to, or problems with relay records (oscillography, demand, fault reports, etc.)
С	Protocols and communications	Changes to, or problems with protocols or communication features
M	Metering	Metering out of specification or other metering problems
Р	Protection out of specification	Protection operates correctly but does not meet published specifications (example: delayed trip)
U	Unavailability of protection	Protection not available in a self-demonstrating way so that corrective actions could be taken immediately
Н	Hidden failure to trip	Protection may not operate when it should
F	False trip	Protection may operate when it should not
В	Unexpected restart	Relay restarts unexpectedly

The revision category letter is placed to the left of the change description.

For further assistance

For product support, contact the information and call center as follows:

GE Grid Solutions

650 Markland Street

Markham, Ontario

Canada L6C 0M1

Worldwide telephone: +1 905 927 7070

Europe/Middle East/Africa telephone: +34 94 485 88 54

North America toll-free: 1 800 547 8629

Fax: +1 905 927 5098

North America - <u>ga.supportnam@ge.com</u> Latin America - <u>ga.supportlam@ge.com</u>

Europe - ga.supportercis@ge.com

Middle East - ga.supportmenat@ge.com

India - ga.supportind@ge.com

China & East Asia Pacific - ga.supportceap@ge.com Website:http://www.gegridsolutions.com/multilin/