



GE VERNOVA

D&I EnerVista Setup Software

D&I EnerVista Setup Software Version 12

Release Notes

Publication Number: GER 5014

Copyright © 2026 GE Vernova

Publication Date: Jan 2026

Summary

GE Vernova releases the D&I EnerVista Setup Software Version 12 for the 8 Series and Multilin Agile Protection & Control Product line.

D&I EnerVista Setup Software Version 12

Release Date: December 15, 2025

- D&I EnerVista Setup Software version 12 supports 8 Series firmware versions 1.1x to 4.3x and Multilin Agile firmware versions 5x to 9x.
- When updating the firmware, files are overwritten and all settings could be lost, always save the setpoint file before upgrading.
- Configuration of the CID file is required to be created or converted from the previous version using, D&I EnerVista Setup v12 or newer
- The latest D&I EnerVista Setup software is available at the same location. The software supports Windows 7, 8.1, 10 and 11.

Note: Please contact your local Multilin sales representative or Multilin Customer Service Department for any questions regarding this upgrade.

Table of Contents

1.1	Last Trip Data	4
1.2	VT settings configuration	4
1.3	Time Multiplier Setting (TMS)	4
1.4	Firmware Version Misread in Compatibility Mode	4
1.5	Clear Thermal Capacity Used (TCU) command removed.....	5
1.6	DNP Protocol Analogue Input and Binary Output	5
1.7	Motor Load averaging – 369 to 859 file conversion	5
1.8	3rd Harmonic Voltage Difference – 489 to 889 file conversion	5
1.9	FlexCurve OL Curve Multiplier – Unhandled Exception	6
1.10	FlexLogic Logic Designer – Unhandled Exception.....	6
1.11	Modbus Slave address change – Unhandled Exception.....	6
1.12	Data CSV files – Unhandled Exception	6
	For Further Assistance	7

D&I Setup Software v12

1.1 Last Trip Data

Section:	Records
Impact to customer:	The Last Trip Data screen has been moved from Records to Status to align with the firmware HMI for 8 Series and Multilin Agile.
Products Affected:	8 Series and Multilin Agile
What changed?	Last trip screen moved to align with HMI firmware.

1.2 VT settings configuration

Section:	Protection
Impact to customer:	Implemented consistency between Quick Setup settings and System > Voltage Sensing settings of VT Secondary value.
Products Affected:	Multilin Agile
What changed?	Corrected data management issues in Multilin Agile ensuring consistency of VT secondary setting.

1.3 Time Multiplier Setting (TMS)

Section:	Protection
Impact to customer:	Resolved the TMS dependency to ensure it is visible when the curve type is set to Inverse Time for Phase Undervoltage (UV) and Phase Overvoltage (OV).
Products Affected:	EnerVista Setup Software v11
What changed?	TMS settings visibility logic updated.

1.4 Firmware Version Misread in Compatibility Mode

Section:	Actual Values
Impact to customer:	The Setup software incorrectly displayed the firmware version when polling 8 Series devices with compatibility mode enabled.
Products Affected:	EnerVista Setup Software v11
What changed?	Corrected Setup behavior when reading the order code from an 8 Series relay in Compatibility Mode.

1.5 Clear Thermal Capacity Used (TCU) command removed

Section:	Commands
Impact to customer:	Previously executing Clear Thermal Capacity Used (TCU) command did not clear the TCU.
Products Affected:	Multilin Agile P24x
What changed?	Removed Clear Thermal Capacity Used (TCU) command from the Commands page. Motor thermal capacity should be cleared via Emergency Restart.

1.6 DNP Protocol Analogue Input and Binary Output

Section:	Communications
Impact to customer:	Unable to configure DNP Analogue Input and Binary Output Object settings list in the Setup Software.
Products Affected:	Multilin Agile
What changed?	Corrected the software logic for displaying setting screens on Multilin Agile.

1.7 Motor Load averaging – 369 to 859 file conversion

Section:	Protection/File Conversion
Impact to customer:	The Motor Load Filter Interval setting was being incorrectly updated during conversion from 369 to 859 settings file.
Products Affected:	859
What changed?	Corrected the file conversion logic to properly update the Motor Load Filter Interval setting.

1.8 3rd Harmonic Voltage Difference – 489 to 889 file conversion

Section:	Protection/File Conversion
Impact to customer:	The 3rd Harmonic Voltage Difference Alarm may become disabled after file conversion from 489 to 889, even if it was enabled on the 489.
Products Affected:	889
What changed?	Corrected the file conversion logic to properly update the 3rd Harmonic Voltage Difference Alarm setting.

1.9 FlexCurve OL Curve Multiplier – Unhandled Exception

Section:	Protection
Impact to customer:	Changing the FlexCurve OL curve multiplier setting could cause the Setup software to crash.
Products Affected:	859, 869
What changed?	Resolved unhandled exception when changing curve multiplier setting on the FlexCurveOL under System > Flexcurve OL > Curve Multiplier

1.10 FlexLogic Logic Designer – Unhandled Exception

Section:	FlexLogic
Impact to customer:	Changing any setting in the FlexLogic Logic Designer could cause the Setup software to crash.
Products Affected:	8 Series EnerVista Setup Software v4.21
What changed?	Corrected error in Logic Designer when editing 8 Series firmware files v1.1x to 3.0x.

1.11 Modbus Slave address change – Unhandled Exception

Section:	FlexLogic
Impact to customer:	Changing Modbus Slave address could cause the Setup software to crash.
Products Affected:	8 Series EnerVista Setup Software v4.11 and D&I Setup Software v11
What changed?	Corrected logic when editing the Modbus Slave address setting.

1.12 Data CSV files – Unhandled Exception

Section:	Records
Impact to customer:	Opening an imported CSV file causes the Setup software to crash.
Products Affected:	8 Series EnerVista Setup Software v4.21
What changed?	Updated the CSV file handling to improve filtering logic when opening files.

For Further Assistance

For questions or further product support, please contact the GE Vernova support team

Region	E-mail	Comments
Global Contact Centre	ga.support@gevernova.com	+44 1785 250070
Central and East Asia and Pacific	ga.supportCEAP@gevernova.com	+61 414 730 964
India	ga.supportIND@gevernova.com	+91 44 22648000
Middle East, North Africa and Turkey	ga.supportMENAT@gevernova.com	+971 42929467
Europe, Russia, CIS and Sub-Saharan Africa	ga.supportERCIS@gevernova.com	+34 94 4858854
North America	ga.supportNAM@gevernova.com	+1 877 605 6777
Latin America	ga.supportLAM@gevernova.com	+55 11 36187308