Date: **Aug 2022** Distribution: **Public** Reference: **RT43X-FW-RN-EN-1**

RT43X Firmware

v 08A07.00 - Aug 2022

Notable bug fixes

- ClockClass keeps value "6" when the RT43x indicates zero satellites.
- GMC accuracy is changed instantaneously when antenna is reconnected.
- RT43x stuck in "LOCKING" state after changing configuration.
- RT43x boot fails when receiving SNMP requests.
- Trailer PRP on PTP packets cause time zone jumps and crashes.
- Clockclass keeps value "7" even without antenna.
- RT43x stops sending PTP packets when "Send Local Time" is enabled.

Hardware compatibility

- Firmware 08A07 is compatible with all hardware versions.

Upgrade procedure

- Upgrading to firmware 08A07 can be done by downloading the upgrade file directly from our website:
  https://www.gegridsolutions.com/measurement_recording_timesync/catalog/rt430.htm
- Firmware versions 01A00 and newer can be upgraded directly to 08A07.

> **After firmware upgrade, user MUST clear web browser's cache for changes to take effect.**

Upgrade impact

- Firmware downgrades are not allowed.

For questions or further product support, please contact the GE support team using:

Region	E-mail	Telephone
Global Contact Centre	GA.support@GE.com	+44 1785 250070
Central, East Asia, Pacific	GA.supportCEAP@GE.com	+61 414 730 964
India	GA.supportIND@GE.com	+91 44 2264 8000
Middle East, North Africa, Turkey	GA.supportMENAT@GE.com	+971 42929467
Europe, Russia, CIS, Sub-Saharan Africa	GA.supportERCIS@GE.com	+34 94 4858854
North America	GA.supportNAM@GE.com	+1 877 605 6777
Latin America	GA.supportLAM@GE.com	+55 48 2108 0300