



MPM Motor Protection Meter

Revision 1.32 release notes

GE Publication Number: GER-4048

Copyright © 2005 GE Multilin

Overview

Summary

- Affected products: MPM Motor Protection Meter
- Date of release: March 23, 2005
- Firmware revision: 1.32

Release summary

This release note covers the version 1.32 firmware release of the MPM Motor Protection Meter. This release has corrected a minor issue with the analog outputs.

GE Multilin technical support

GE Multilin contact information and call center for product support is shown below:

GE Multilin
215 Anderson Avenue
Markham, Ontario
Canada L6E 1B3

Telephone: 905-294-6222 or 1-800-547-8629 (North America), +34 94 485 88 00 (Europe)
Fax: 905-201-2098 (North America), +34 94 485 88 45 (Europe)

E-mail: multilin.tech@ge.com

Home Page: <http://www.GEmultilin.com>

Release details

Modified features

Analog Outputs: temporary disabling upon power-up corrected

For MPM firmware versions 1.30 to 1.31, one or more of the analog outputs may have been temporarily disabled upon power-up. This would automatically correct itself after approximately 7 to 10 minutes, at which point the analog output would recover and continue to work correctly. The firmware has been modified to correct this issue.

Upgrading product firmware/software

Refer to page 6-7 of the MPM instruction manual (publication number 1601-0075-C1) or contact the GE Multilin customer service department for assistance.

- Firmware File Name: 70C132C4.000
- Software Upgrade Procedure: Contact GE Multilin for upgrade.