

MultiSync 100 1588 GPS Clock End-of-Manufacturing Notice

Excerpt from GE Publication Number: GER-4820

Issue Date: February 28th, 2018

Copyright © 2018 GE Multilin Inc.

Background

GE Grid Solutions is committed to customer care and the support of our products. As part of this commitment, GE strives to design high quality products, provide knowledge-based support, and to communicate the availability of new features or products as well as the pending discontinuation of manufacturing for older products or design variants.

GE Grid Solutions is discontinuing the manufacture and sale of **MultiSync 100 1588 GPS clocks** due to a component obsolescence, with alternatives available in the **Reason RT43x range of satellite clocks**. This notice does not apply to any other model not explicitly listed.

Last-Time Buy Window

The table which follows outlines the strategy for the affected product(s) - within your organization please plan now the purchase of any additional or spare devices that you feel you may need. Such orders should be routed to us prior to the date shown, with the last delivery date expected no later than that shown in the table.

PRODUCT	LAST ORDER DATE	LAST DELIVERY DATE	ALTERNATIVE
MultiSync 100 1588 GPS Clock, order code MultiSync100-P	9 th July 2018	1st October 2018	Reason RT431 (for limited mounting space applications) Reason RT430 (for 19" rackmount installation, GNSS, and PRP networks applications) Reason RT434 (for 19" rackmount installation and GNSS applications)

Visit our website at <http://www.gegridsolutions.com/multilin/selector/> for more information about alternative products.

For Additional Information

If we can provide assistance with migration to new products, please contact us for help. Advice and assistance is also available via:

<http://www.gegridsolutions.com/contact.htm?loc=3> or

<http://www.gegridsolutions.com/multilin>