

## MultiLink Switch Family 10Mb Fiber Ports End-of-Manufacturing Notice

### Excerpt from GE Publication Number: GER-4820

Issue Date: February 28<sup>th</sup>, 2018

Copyright © 2018 GE Multilin Inc.

---

### Background

GE Grid Solutions is committed to customer care and the support of our products. As part of this commitment, GE strives to design high quality products, provide knowledge-based support, and to communicate the availability of new features or products as well as the pending discontinuation of manufacturing for older products or design variants.

GE Grid Solutions is discontinuing the manufacture and sale of **10Mb fiber optic ports for the MultiLink Ethernet Switch Family models** due to a component obsolescence. This notice does not apply to any other model not explicitly listed.

| PRODUCT   | ORDERING STATUS   | ALTERNATIVE                          |
|---|-------------------|--------------------------------------|
| ML810<br>EL (2x10FL / 2x100FX) and EM (4x10FL)<br>port module options | Order Book Closed | Convert to 100Mbit and Gigabit ports |
| ML1200<br>C7 (2x10Mbit) port module option                            | Order Book Closed | Convert to 100Mbit and Gigabit ports |
| ML3000/ML3001<br>D (2x10Mbit) port module option for<br>slots 3-10    | Order Book Closed | Convert to 100Mbit and Gigabit ports |
| ML3100/ML3101<br>D (2x10Mbit) port module option for<br>slots 5-8     | Order Book Closed | Convert to 100Mbit and Gigabit ports |

Visit our website at <http://www.gegridsolutions.com/multilin/selector/> for more information about alternative products.

### For Additional Information

If we can provide assistance with migration to new products, please contact us for help. Advice and assistance is also available via:

<http://www.gegridsolutions.com/contact.htm?loc=3> or

<http://www.gegridsolutions.com/multilin>