



Software 35, 42, & 43 for P141, P143, & P145 End-of-Manufacturing/Supply Notice

Excerpt from Publication Number: GER-4844

Issued: 22nd October 2018

- 5th December 2025 (Rebranding Revisions)

Copyright © 2025 GE Vernova

Background

GE Vernova Grid Solutions is committed to customer care and the support of our offerings. As part of this commitment, we strive to design high quality offerings, provide knowledge-based support, and to communicate the availability of new features or offerings as well as the pending discontinuation of manufacturing for older offerings or design variants.

On 22nd October 2018, the discontinuation of the manufacturing and supply of Software 35, 42, & 43 for P141, P143, & P145 was announced.

On 5th December 2025, the alternatives were revised to include descriptions, and this notice was revised in accordance with GE Vernova rebranding guidelines.

Last-Time Buy Window

Please plan the purchase of any additional quantities or spares that you need. Orders should be placed prior to the last order date shown. Orders will be fulfilled based upon availability and shipments typically occur within three months of last order date. Requests for delayed shipments must be agreed with our factories prior to order acceptance.

OFFERING	LAST ORDER DATE	ALTERNATIVE
Software 35 for P141	1 st December 2018	P141 Software 61 (IEC 61850 Ed. 2) Hardware P or P141 Software 52 (IEC 61850 Ed.1) Hardware J
Software 35 for P143	1 st December 2018	P143 Software 61 (IEC 61850 Ed. 2) Hardware P or P143 Software 52 (IEC 61850 Ed.1) Hardware J
Software 35 for P145	1 st December 2018	P145 Software 61 (IEC 61850 Ed. 2) Hardware P or P145 Software 52 (IEC 61850 Ed.1) Hardware J
Software 42 for P141	1 st December 2018	P141 Software 61 (IEC 61850 Ed. 2) Hardware P or P141 Software 52 (IEC 61850 Ed.1) Hardware J
Software 42 for P143	1 st December 2018	P143 Software 61 (IEC 61850 Ed. 2) Hardware P or P143 Software 52 (IEC 61850 Ed.1) Hardware J

OFFERING	LAST ORDER DATE	ALTERNATIVE
Software 42 for P145	1 st December 2018	P145 Software 61 (IEC 61850 Ed. 2) Hardware P or P145 Software 52 (IEC 61850 Ed.1) Hardware J
Software 43 for P141	1 st December 2018	P141 Software 61 (IEC 61850 Ed. 2) Hardware P or P141 Software 52 (IEC 61850 Ed.1) Hardware J
Software 43 for P143	1 st December 2018	P143 Software 61 (IEC 61850 Ed. 2) Hardware P or P143 Software 52 (IEC 61850 Ed.1) Hardware J
Software 43 for P145	1 st December 2018	P145 Software 61 (IEC 61850 Ed. 2) Hardware P or P145 Software 52 (IEC 61850 Ed.1) Hardware J

Support

GE Vernova's warranty provision is unaffected by this End-of-Manufacturing/Supply Notification. After the published last order date elapses, a repair service follows for items no longer under warranty subject to availability that includes repairing failed components or modules, but not to providing advanced replacements or a new product or module as a replacement or spare.

Customers should contact us if they need further information concerning the level of service that is provided on a per offering basis.

For Additional Information

If we can provide assistance with migration to new offerings, please contact us for help. Advice and assistance are also available via: <https://www.gevernova.com/grid-solutions/contact.htm?loc=3> or <https://www.gevernova.com/grid-solutions/automation/protection-control-metering>.