



Hardware Options J, K, N, & P for MiCOM 4th Generation Relays End-of-Manufacturing/Supply Notice

Excerpt from Publication Number: GER-4885

Issued: 30th June 2020

Revision Dates:

- 15th December 2020 (Excerpt from End-of-Manufacturing Notice GER-4900)
- 10th May 2021 (Excerpt from End-of-Manufacturing Notice GER-4912)
- 27th May 2022 (Excerpt from End-of-Manufacturing Notice GER-4927)
- 12th December 2022 (Excerpt from End-of-Manufacturing Notice GER-4938)
- 12th December 2024 (Excerpt from End-of-Manufacturing Notice GER-4978)
- 13th November 2025 (Rebranding Revisions)
- 1st June 2026 (Excerpt from End-of-Manufacturing Notice GER-5022)

Copyright © 2026 GE Vernova

Background

GE Vernova Grid Solutions is committed to customer care and the support of our offerings. As part of this commitment, we strive to design high quality offerings, provide knowledge-based support, and to communicate the availability of new features or offerings as well as the pending discontinuation of manufacturing for older offerings or design variants.

On 30th June 2020, the discontinuation of the manufacturing and supply of Hardware Options J, K, N, & P for Selected MiCOM Models in rows 3 and 4 of the table below was announced with a last order date of 31st December 2020.

On 15th December 2020, the last order date for Hardware J, K, N, & P for P442 Software 72 & 83, and P444 Software 72 & 83 as shown in row 4 of the table below was extended to 30th April 2021. The discontinuation of the manufacturing and sales of Hardware Options J, K, N, & P for P645 in row 5 of the table below was also announced.

On 10th May 2021, the discontinuation of the manufacturing and sales of Hardware Options J, K, N, & P for the additional MiCOM models shown in rows 6 and 7 of the table below was announced.

On 27th May 2022, the discontinuation of the manufacturing and sales of Hardware Options J, K, N, & P for P444 Software 83 & 86, P446, P546, & P841 Software 86, and P645 Software 22 was announced (second posting corrected typo in date).

On 12th December 2022, the retraction of 27th May 2022 announcement of Hardware Options J, K, N, & P for P444 Software 83 & 86, P446, P546, & P841 Software 86, and P645 Software 22 was published as these offerings were previously announced and obsoleted.

On 12th December 2024, the discontinuation of the manufacturing and sales of Hardware Options J, K, N, & P was retracted for the following models: P442/4 Software 72 & 83, P44T Software 02, and P543 Software 76, which remain available for sale, subject to availability. The alternatives in the following table were

revised to Contact GE Vernova. This notice was revised in accordance with GE Vernova rebranding guidelines.

On 13th November 2025, this notice was revised in accordance with GE Vernova rebranding guidelines.

On 1st June 2026, the discontinuation of the manufacturing and sales of Hardware Options J, K, N, & P for all remaining active MiCOM 4th Generation models and software versions that were not previously published were announced. The alternatives in the following table were revised to Contact Us. The row numbers in the background section were revised to reflect that two new rows were added at the beginning of the table below.

Last-Time Buy Window

Please plan the purchase of any additional quantities or spares that you need. Orders should be placed prior to the last order date shown. Orders will be fulfilled based upon availability and shipments typically occur within three months of last order date. Requests for delayed shipments must be agreed with our factories prior to order acceptance.

OFFERING	LAST ORDER DATE	ALTERNATIVE
MiCOM Hardware Options J & K For All Remaining Active Models and Software Versions Not Specified In the Rows Below J - Redundant Ethernet RSTP, 2 Multimode Fibre Ports + Modulated IRIG-B K - Redundant Ethernet RSTP, 2 Multimode Fibre Ports + Un-Modulated IRIG-B Order Codes: PxxxxxJxxxxxxxxx PxxxxxKxxxxxxxxx	30 th November 2027	MiCOM 5th Generation Hardware Options U, V, W, or Y On Software AB: U - Single Ethernet 1 LC Duplex Port + Universal IRIG-B + 1 RJ45 Maintenance Port V - Redundant Ethernet PRP/HSR/RSTP/Failover 2 LC Duplex Port + IEC870-103 Serial Fibre ST Ports + Universal IRIG-B + 1588 + 1 RJ45 Maintenance Port W - Redundant Ethernet PRP/HSR/RSTP/Failover 2 RJ45 + Universal IRIG-B + 1588 + 1 RJ45 Maintenance Port Y - Redundant Ethernet PRP/HSR/RSTP/Failover 2 LC Duplex Ports + Universal IRIG-B + 1588 + 1 RJ45 Maintenance Port or MiCOM 4th Generation Hardware Options 6, A, B, U, W, or Y 6 - Ethernet (100 Mbps) A - Ethernet (100 Mbit/s) Plus IRIG-B (Modulated) B - Ethernet (100 Mbit/s) Plus IRIG-B (Un-Modulated) U - Single Ethernet 1 LC Duplex Port + Universal IRIG-B + 1 RJ45 Maintenance Port W - Redundant Ethernet PRP/HSR/RSTP/Failover 2 RJ45 +

OFFERING	LAST ORDER DATE	ALTERNATIVE
		Universal IRIG-B + 1588 + 1 RJ45 Maintenance Port Y - Redundant Ethernet PRP/HSR/RSTP/Failover 2 LC Duplex ports + Universal IRIG-B + 1588 + 1 RJ45 Maintenance Port As Applicable To MiCOM Model And SW Version
MiCOM Hardware Options N & P For All Remaining Active Models and Software Versions Not Specified In the Rows Above N - Redundant Ethernet PRP/HSR, 2 Fibre Ports + Modulated IRIG-B P - Redundant Ethernet PRP/HSR, 2 Fibre Ports + Un-Modulated IRIG-B Order Codes: PxxxxxNxxxxxxxxx PxxxxxPxxxxxxxxx	Contact Us For Availability	MiCOM 5th Generation Hardware Options U, V, W, or Y On Software AB: U - Single Ethernet 1 LC Duplex Port + Universal IRIG-B + 1 RJ45 Maintenance Port V - Redundant Ethernet PRP/HSR/RSTP/Failover 2 LC Duplex Port + IEC870-103 Serial Fibre ST Ports + Universal IRIG-B + 1588 + 1 RJ45 Maintenance Port W - Redundant Ethernet PRP/HSR/RSTP/Failover 2 RJ45 + Universal IRIG-B + 1588 + 1 RJ45 Maintenance Port Y - Redundant Ethernet PRP/HSR/RSTP/Failover 2 LC Duplex Ports + Universal IRIG-B + 1588 + 1 RJ45 Maintenance Port or MiCOM 4th Generation Hardware Options 6, A, B, U, W, or Y 6 - Ethernet (100 Mbps) A - Ethernet (100 Mbit/s) Plus IRIG-B (Modulated) B - Ethernet (100 Mbit/s) Plus IRIG-B (Un-Modulated) U - Single Ethernet 1 LC Duplex Port + Universal IRIG-B + 1 RJ45 Maintenance Port W - Redundant Ethernet PRP/HSR/RSTP/Failover 2 RJ45 + Universal IRIG-B + 1588 + 1 RJ45 Maintenance Port Y - Redundant Ethernet PRP/HSR/RSTP/Failover 2 LC Duplex ports + Universal IRIG-B + 1588 + 1 RJ45 Maintenance Port As Applicable To MiCOM Model And SW Version

OFFERING	LAST ORDER DATE	ALTERNATIVE
MiCOM Hardware Options: J - Redundant Ethernet RSTP, 2 Multimode Fibre Ports + Modulated IRIG-B K - Redundant Ethernet RSTP, 2 Multimode Fibre Ports + Unmodulated IRIG-B N - Redundant Ethernet PRP/HSR, 2 Fibre Ports + Unmodulated IRIG-B P - Redundant Ethernet PRP/HSR, 2 Fibre Ports + Unmodulated IRIG-B On The Following Models: P241/2/3 SW 60 P442 SW 71 P443 SW 87 P444 SW 71 & 86 P445 SW 46 & 49 P446 SW 86 P543 SW 87 P545 SW 87 P546 SW 86 P841 SW 86	31 st December 2020	Contact Us
MiCOM Hardware Options: J - Redundant Ethernet RSTP, 2 multi-mode fibre ports + Modulated IRIG-B K - Redundant Ethernet RSTP, 2 multi-mode fibre ports + Unmodulated IRIG-B N - Redundant Ethernet PRP/HSR, 2 fibre ports + Unmodulated IRIG-B P - Redundant Ethernet PRP/HSR, 2 fibre ports + Unmodulated IRIG-B On The Following Models: P442 SW 72 & 83 – Retracted P444 SW 72 & 83 – Retracted	30 th April 2021 Retracted	Contact Us
MiCOM Hardware Options: J - Redundant Ethernet RSTP, 2 Multimode Fibre Ports + Modulated IRIG-B K - Redundant Ethernet RSTP, 2 Multimode Fibre Ports + Unmodulated IRIG-B N - Redundant Ethernet PRP/HSR, 2 Fibre Ports + Unmodulated IRIG-B P - Redundant Ethernet PRP/HSR, 2 Fibre Ports + Unmodulated IRIG-B On The Following Model: P645 SW 22	15 th June 2021	Contact Us

End-of-Manufacturing/Supply Notice

OFFERING	LAST ORDER DATE	ALTERNATIVE
MiCOM Hardware Options: J - Redundant Ethernet RSTP, 2 Multimode Fibre Ports + Modulated IRIG-B K - Redundant Ethernet RSTP, 2 Multimode Fibre Ports + Unmodulated IRIG-B N - Redundant Ethernet PRP/HSR, 2 Fibre Ports + Unmodulated IRIG-B P - Redundant Ethernet PRP/HSR, 2 Fibre Ports + Unmodulated IRIG-B On The Following Models P141/2/3/5 SW 51 P141/2/3/5 SW 52 P44T SW 02 Retracted P443/6 SW 76 P543 SW 76 Retracted P544/5 SW 76 P546 SW 79 P841 SW 66 & 76	30th June 2022	Contact Us
MiCOM Hardware Options: J - Redundant Ethernet RSTP, 2 Multimode Fibre Ports + Modulated IRIG-B K - Redundant Ethernet RSTP, 2 Multimode Fibre Ports + Unmodulated IRIG-B N - Redundant Ethernet PRP/HSR, 2 Fibre Ports + Unmodulated IRIG-B P - Redundant Ethernet PRP/HSR, 2 Fibre Ports + Unmodulated IRIG-B On The Following Models: P443 SW 71 P546 SW 71	30th October 2022	Contact Us

Support

GE Vernova's warranty provision is unaffected by this End-of-Manufacturing/Supply Notification. After the published last order date elapses, a repair service follows for items no longer under warranty subject to availability that includes repairing failed components or modules, but not to providing advanced replacements or a new product or module as a replacement or spare.

Customers should contact us if they need further information concerning the level of service that is provided on a per offering basis.

For Additional Information

If we can provide assistance with migration to new offerings, please contact us for help. Advice and assistance are also available via: <https://www.gevernova.com/grid-solutions/contact.htm?loc=3> or <https://www.gevernova.com/grid-solutions/automation/protection-control-metering>.