



# Release Notes

Date: **14 November 2025**Distribution: **Public**Reference: **S20-FW-RN-EN-1**

## S20 switches Release Notes

### References

Publication number	S20-FW-RN-EN-1
Firmware Release	07A08.04
Release date	14 November 2025

### Key New Features

- GE Vernova rebranding

### Notable bug fixes

- Fixed duplicated log messages.
- Fixed web browser connection instability
- Fixed issue with HTTPS session timeout not reporting properly
- Changed CPU Load alarm trigger interval
- Fixed SNMPv3 issue
- Added log entries for user lockout and third failed attempt to login

### Hardware compatibility

- Firmware 07A08.04 is compatible with hardware version B and C.

### Upgrade procedure

- Upgrade directly from firmware 06A02.00 or newer
- Follow process outlined in S20 technical manual, chapter 7, section 2.3.
- When performing firmware upgrade, please make sure to save the running configuration to the startup between each upgrade.
- After firmware upgrade, please clear the web browser's cache for changes to take effect.

### Upgrade impact

- Firmware downgrades are not allowed

## For Product Support

For questions or further product support, please contact the GE support team using:

Region	E-mail	Telephone
Global Contact Centre	ga.support@gevernova.com	+44 1785 250070
Central, East Asia, Pacific	ga.supportCEAP@gevernova.com	+61 414 730 964
India	ga.supportIND@gevernova.com	+91 44 2264 8000
Middle East, North Africa, Turkey	ga.supportMENAT@gevernova.com	+971 4 375 6950
Europe, Russia, CIS, Sub-Saharan Africa	ga.supportERCIS@gevernova.com	+34 94 485 8854
North America	ga.supportNAM@gevernova.com	+1 877 605 6777
Latin America	ga.supportLAM@gevernova.com	+55 48 2108 0300

## Document revision history

Version	Date	Change Description
S20-FW-RN-EN-1	14 November 2025	Initial release

## Disclaimer:

Unless the product is under a GE Vernova service contract, GE Vernova assumes no responsibility or liability for the content of Release Notes or for making Release Notes available to customer.

Performing updates/upgrades to software/firmware is solely the responsibility of the customer.