



Hardware Options R, S, & T for MiCOM End-of-Manufacturing/Supply Notice

Excerpt from Publication Number: GER-4978

Issued: 12th December 2024

Revision Dates:

- 10th June 2025 (Excerpt from End-of-Manufacturing Notice GER-5001)
- 22nd November 2025 (Rebranding Revisions)
- 24th November 2025 (Excerpt from End-of-Manufacturing Notice GER-5008)
- 1st June 2026 (Excerpt from End-of-Manufacturing Notice GER-5022)

Copyright © 2026 GE Vernova

Background

GE Vernova Grid Solutions is committed to customer care and the support of our offerings. As part of this commitment, we strive to design high quality offerings, provide knowledge-based support, and to communicate the availability of new features or offerings as well as the pending discontinuation of manufacturing for older offerings or design variants.

On 12th December 2024, the discontinuation of the manufacturing and supply of Hardware Options R, S, & T for MiCOM was announced.

In the table below, please note the following:

- Hardware options J, K, N and P have been restored for items marked with *
- Hardware options J, K, N and P have been enabled for items marked with **

On 10th June 2025, a new entry for P141/2/3/5 SW91 was added to highlight the new alternatives available for this offering and this notice was revised in accordance with GE Vernova rebranding guidelines.

On 22nd November 2025, this notice was revised in accordance with GE Vernova rebranding guidelines.

On 24th November 2025, the offering was revised to include P84 MiCOM 5th Gen SW AA, and SW 91 for P443, P543/5, P642/3, & P741/3. The last time buy for the following expired in line with the software version status: P141/2/3 SW51 & 52, P241/2/3 SW60, P443 SW76, 79, & 87, P446 SW76 & 82, P543 SW76 & 79, P545 SW76 & 79, P546 SW76, P643 SW21, P741 SW70, P747 SW03, & P841 SW69, 79, 81, & 82. The consolidated notice incorrectly removed the following items which have been reinstated in this excerpt consistent with the software version status: P442 SW72 & 83 & P444 SW72 & 83.

On 1st June 2026, the offering was revised to include P442/4 SW 92, P746 SW91, and P141/2/3/5 SW61. The alternatives were revised to exclude Hardware Options N & P. The last time buy for the following expired in line with the software version status: MiCOM 5th Gen SW AA, P442 SW72 & 83, and P444 SW72 & 83.

Last-Time Buy Window

Please plan the purchase of any additional quantities or spares that you need. Orders should be placed prior to the last order date shown. Orders will be fulfilled based upon availability and shipments typically occur within three months of last order date. Requests for delayed shipments must be agreed with our factories prior to order acceptance.

OFFERING	LAST ORDER DATE	ALTERNATIVE
Hardware Options R, S, & T For MiCOM Relays (All Items Not Specified In The Rows Below)	Contact Us For Availability	MiCOM 5th Generation Hardware Options U, V, W, or Y On Software AB: U – Single Ethernet 1 LC Duplex Port + Universal IRIG-B + 1 RJ45 Maintenance Port V – Redundant Ethernet PRP/HSR/RSTP/Failover 2 LC Duplex Port + IEC870-103 Serial Fibre ST Ports + Universal IRIG-B + 1588 + 1 RJ45 Maintenance Port W – Redundant Ethernet PRP/HSR/RSTP/Failover 2 RJ45 + Universal IRIG-B + 1588 + 1 RJ45 Maintenance Port Y – Redundant Ethernet PRP/HSR/RSTP/Failover 2 LC Duplex Ports + Universal IRIG-B + 1588 + 1 RJ45 Maintenance Port or MiCOM 4th Generation Hardware Options J, K, 6, A, or B J – Redundant Ethernet RSTP, 2 Multimode Fibre Ports + Modulated IRIG-B K – Redundant Ethernet RSTP, 2 Multimode Fibre Ports + Unmodulated IRIG-B 6 – Ethernet (100 Mbps) A – Ethernet (100 Mbit/s) Plus IRIG-B (Modulated) B – Ethernet (100 Mbit/s) Plus IRIG-B (Unmodulated) As Applicable To MiCOM Model & SW Version
Hardware Options R, S, & T For MiCOM 5th Generation Software AA: R – Redundant Ethernet PRP/HSR/RSTP/Hot Standby, 2 Multimode Fibre Ports + Modulated/Unmodulated IRIG-B S – Redundant Ethernet PRP/HSR/RSTP/Hot Standby, 2 Copper Ports RJ45 + Modulated/Unmodulated IRIG-B T – Single & Redundant Ethernet Failover: 1 Copper Port RJ45 + 1 Multimode Fibre Port + Modulated/Unmodulated IRIG-B On The Following Models & Software Versions: P44 MiCOM 5th Gen SW AA P54 MiCOM 5th Gen SW AA P84 MiCOM 5th Gen SW AA	Contact Us For Availability	MiCOM 5th Generation Hardware Options U, V, W, or Y On Software AB: U – Single Ethernet 1 LC Duplex Port + Universal IRIG-B + 1 RJ45 Maintenance Port V – Redundant Ethernet PRP/HSR/RSTP/Failover 2 LC Duplex Port + IEC870-103 Serial Fibre ST Ports + Universal IRIG-B + 1588 + 1 RJ45 Maintenance Port W – Redundant Ethernet PRP/HSR/RSTP/Failover 2 RJ45 + Universal IRIG-B + 1588 + 1 RJ45 Maintenance Port Y – Redundant Ethernet PRP/HSR/RSTP/Failover 2 LC Duplex Ports + Universal IRIG-B + 1588 + 1 RJ45 Maintenance Port

OFFERING	LAST ORDER DATE	ALTERNATIVE
Hardware Options R, S, & T For MiCOM 4th Generation R – Redundant Ethernet PRP/HSR/RSTP/Hot Standby, 2 Multimode Fibre Ports + Modulated/Unmodulated IRIG-B S – Redundant Ethernet PRP/HSR/RSTP/Hot Standby, 2 Copper Ports RJ45 + Modulated/Unmodulated IRIG-B T – Single & Redundant Ethernet Failover: 1 Copper Port RJ45 + 1 Multimode Fibre Port + Modulated/Unmodulated IRIG-B On The Following Models & Software Versions: P141/2/3/5 SW91 P442/4 SW92 P443 SW91 P543/5 SW91 P642/3 SW91 P741/3 SW91 P746 SW91	Contact Us For Availability	MiCOM 4th Generation Hardware Options U, W, or Y On Software 91: U - Single Ethernet 1 LC Duplex Port + Universal IRIG-B +1588 W - Redundant Ethernet PRP/HSR/RSTP/Failover 2 RJ45 + Universal IRIG-B + 1588 Y - Redundant Ethernet PRP/HSR/RSTP/Failover 2 LC Duplex Ports + Universal IRIG-B + 1588
Hardware Options R, S, & T For MiCOM 4th Generation R – Redundant Ethernet PRP/HSR/RSTP/Hot Standby, 2 Multimode Fibre Ports + Modulated/Unmodulated IRIG-B S – Redundant Ethernet PRP/HSR/RSTP/Hot Standby, 2 Copper Ports RJ45 + Modulated/Unmodulated IRIG-B T – Single & Redundant Ethernet Failover: 1 Copper Port RJ45 + 1 Multimode Fibre Port + Modulated/Unmodulated IRIG-B On The Following Models And Software Versions: P141/2/3/5 SW61 P241/2/3 SW60 P445 SW49 P546 SW79	Contact Us For Availability	MiCOM 4th Generation Hardware Options 6, A, or B 6 – Ethernet (100 Mbps) A – Ethernet (100 Mbit/s) Plus IRIG-B (Modulated) B – Ethernet (100 Mbit/s) Plus IRIG-B (Unmodulated)
Hardware Options R, S, & T For MiCOM 4th Generation R – Redundant Ethernet PRP/HSR/RSTP/Hot Standby, 2 Multimode Fibre Ports + Modulated/Unmodulated IRIG-B S – Redundant Ethernet PRP/HSR/RSTP/Hot Standby, 2 Copper Ports RJ45 + Modulated/Unmodulated IRIG-B T – Single & Redundant Ethernet Failover: 1 Copper Port RJ45 + 1 Multimode Fibre Port + Modulated/Unmodulated IRIG-B On The Following Models And Software Versions: P743 SW51 P743 SW70	Contact Us For Availability	MiCOM 4th Generation Hardware Options 6, J, or K 6 – Ethernet (100 Mbps) J – Redundant Ethernet RSTP, 2 Multimode Fibre Ports + Modulated IRIG-B K – Redundant Ethernet RSTP, 2 Multimode Fibre Ports + Unmodulated IRIG-B

OFFERING	LAST ORDER DATE	ALTERNATIVE
Hardware Options R, S, & T For MiCOM 4th Generation R – Redundant Ethernet PRP/HSR/RSTP/Hot Standby, 2 Multimode Fibre Ports + Modulated/Unmodulated IRIG-B S – Redundant Ethernet PRP/HSR/RSTP/Hot Standby, 2 Copper Ports RJ45 + Modulated/Unmodulated IRIG-B T – Single & Redundant Ethernet Failover: 1 Copper Port RJ45 + 1 Multimode Fibre Port + Modulated/Unmodulated IRIG-B On The Following Models And Software Versions: P442 SW72* P442 SW83* P443 SW82 P444 SW72* P444 SW83* P543 SW82 P545 SW82 P546 SW82 P642 SW07 P643 SW07 P645 SW07 P746 SW12	Contact Us For Availability	MiCOM 4th Generation Hardware Options, 6, A, B, J, or K 6 – Ethernet (100 Mbps) A – Ethernet (100 Mbit/s) Plus IRIG-B (Modulated) B – Ethernet (100 Mbit/s) Plus IRIG-B (Unmodulated) J – Redundant Ethernet RSTP, 2 Multimode Fibre Ports + Modulated IRIG-B K – Redundant Ethernet RSTP, 2 Multimode Fibre Ports + Unmodulated IRIG-B
Hardware Options R, S, & T For MiCOM 4th Generation R – Redundant Ethernet PRP/HSR/RSTP/Hot Standby, 2 Multimode Fibre Ports + Modulated/Unmodulated IRIG-B S – Redundant Ethernet PRP/HSR/RSTP/Hot Standby, 2 Copper Ports RJ45 + Modulated/Unmodulated IRIG-B T – Single & Redundant Ethernet Failover: 1 Copper Port RJ45 + 1 Multimode Fibre Port + Modulated/Unmodulated IRIG-B On The Following Models And Software Versions: P241 SW70** P242 SW70** P243 SW 70** P44T SW02*	Contact Us For Availability	MiCOM 4th Generation Hardware Options J, or K J – Redundant Ethernet RSTP, 2 Multimode Fibre Ports + Modulated IRIG-B K – Redundant Ethernet RSTP, 2 Multimode Fibre Ports + Unmodulated IRIG-B

Support

GE Vernova's warranty provision is unaffected by this End-of-Manufacturing/Supply Notification. After the published last order date elapses, a repair service follows for items no longer under warranty subject to availability that includes repairing failed components or modules, but not to providing advanced replacements or a new product or module as a replacement or spare.

Customers should contact us if they need further information concerning the level of service that is provided on a per offering basis.

For Additional Information

If we can provide assistance with migration to new offerings, please contact us for help. Advice and assistance are also available via: <https://www.gevernova.com/grid-solutions/contact.htm?loc=3> or <https://www.gevernova.com/grid-solutions/automation/protection-control-metering>.