

GE Grid Solutions

MCP RDHMI v310.x y.z Changelog

All notable changes to MCP RDHMI v310 will be documented in this file.

MCP RDHMI v310 is based on MCP RDHMI v300.2551-1.0.

MCP RDHMI v310.x-y.z should be used with MCP v3.1 only.

The format is based on [Keep a Changelog](#),

[310.153-1.0] - 2023-08-21

Changed

- Updated the MCP HMI Viewer application to version 3.1.153.

Fixed

- Resolved issue with Firefox failing to launch mapped URL and online help.

Types of changes

- **Added** for new features.
- **Changed** for changes in existing functionality.
- **Deprecated** for soon-to-be removed features.
- **Removed** for now removed features.
- **Fixed** for any issue fixes.
- **Security** in case of vulnerability fixes.