

GE

Grid Solutions

Hardware Options N, P, Q & R for P40 Agile End-of-Manufacturing Notice

Excerpt from GE Publication Number: GER-4938

Issued: 12th December 2022

Revision Date:

- 18th December 2023 (Excerpt from End-of-Manufacturing Notice GER-4956)

Copyright © 2023 General Electric

Background

GE Grid Solutions is committed to customer care and the support of our products. As part of this commitment, GE strives to design high quality products, provide knowledge-based support, and to communicate the availability of new features or products as well as the pending discontinuation of manufacturing for older products or design variants.

On December 12th, 2022, GE Grid Solutions announced the discontinuation of the manufacture and sale of **Hardware Options N, P, Q & R for P40 Agile**.

On 18th December 2023, the alternatives were revised as shown below.

Last-Time Buy Window

Please plan the purchase of any additional or spare devices that you feel you may need. Orders should be placed prior to the last order date shown. **Orders will be fulfilled based upon availability** and products typically ship within three months of the last order date. Requests for delayed shipments must be agreed with our factories prior to order acceptance.

PRODUCT	LAST ORDER DATE	ALTERNATIVE
<p>P40 Agile Hardware Options N, P, Q & R Options: N - EIA RS485/IRIG-B (demodulated) and Dual Copper Ethernet – 2x RJ45 Copper (dual IP) P - EIA RS485/IRIG-B (demodulated) and Dual Redundant Fibre Ethernet – 2x multimode fibre (dual IP) Q – EIA RS485, EIA RS485/IRIG-B (demodulated) and Dual Copper Ethernet – 2x RJ45 Copper (dual IP) R – EIA RS584, EIA RS485/IRIG-B (demodulated) and Dual Redundant Fibre Ethernet – 2x multimode fibre (dual IP) Order Cdes: P14DxxNxxxxxxxx P14NxxNxxxxxxxx P94VxxNxxxxxxxx P14DxxPxxxxxxxx P14NxxPxxxxxxxx P94VxxPxxxxxxxx P14DxxQxxxxxxxx P14NxxQxxxxxxxx P94VxxQxxxxxxxx P14DxxRxxxxxxxx P14NxxRxxxxxxxx P94VxxRxxxxxxxx</p>	<p>1st November 2023</p>	<p>Multilin Agile Hardware Options A, B, or C Options: A – 2x EIA RS485 serial, 2x RJ45 Ethernet (configurable PRP/HSR/LLA) and 1x RJ45 B - 2x EIA RS485 serial, 2x fiber Ethernet (configurable PRP/HSR/LLA) and 1x RJ45 C – 2x EIA RS485 serial, 2x fiber Ethernet (configurable PRP/HSR/LLA) and 1x fiber Order codes: P14DxxAxxxxxxxxE P14NxxAxxxxxxxxE P94VxxAxxxxxxxxE P14DxxBxxxxxxxxE P14NxxBxxxxxxxxE P94VxxBxxxxxxxxE P14DxxCxxxxxxxxE P14NxxCxxxxxxxxE P94VxxCxxxxxxxxE</p>
<p>P40 Agile Hardware Options N, P, Q & R Options: N - EIA RS485/IRIG-B (demodulated) and Dual Copper Ethernet – 2x RJ45 Copper (dual IP) P - EIA RS485/IRIG-B (demodulated) and Dual Redundant Fibre Ethernet – 2x multimode fibre (dual IP) Q – EIA RS485, EIA RS485/IRIG-B (demodulated) and Dual Copper Ethernet – 2x RJ45 Copper (dual IP) R – EIA RS584, EIA RS485/IRIG-B (demodulated) and Dual Redundant Fibre Ethernet – 2x multimode fibre (dual IP) Order codes: P24DxxNxxxxxxxx P24NxxNxxxxxxxx P24DxxPxxxxxxxx P24NxxPxxxxxxxx P24DxxQxxxxxxxx P24NxxQxxxxxxxx P24DxxRxxxxxxxx P24NxxRxxxxxxxx</p>	<p>1st November 2023</p>	<p>P40 Agile Hardware Options E, F, L or M Options: E – EIA RS485/IRIG-B (demodulated) and Dual Redundant Copper Ethernet – 2x RJ45 Copper (setting configurable as PRP or HSR) F - EIA RS485/IRIG-B (demodulated) and Dual Redundant Fibre Ethernet – 2x multimode fibre (setting configurable as PRP or HSR) L – EIA RS485, EIA RS485/IRIG-B (demodulated) and Dual Redundant Copper Ethernet – 2x RJ45 Copper (setting configurable as PRP or HSR) M – EIA RS584, EIA RS485/IRIG-B (demodulated) and Dual Redundant Fibre Ethernet – 2x multimode fibre (setting configurable as PRP or HSR) Order codes: P24DxxExxxxxxxx P24NxxExxxxxxxx P24DxxFxxxxxxxx P24NxxFxxxxxxxx P24DxxLxxxxxxxx P24NxxLxxxxxxxx P24DxxMxxxxxxxx P24NxxMxxxxxxxx</p>

Support

GE’s warranty provision is unaffected by this End-of-Manufacturing Notification. After the published last order date elapses, a repair service follows for products no longer under warranty subject to material availability that includes

End-of-Manufacturing Notice

repairing failed components or modules, but not to providing advanced replacements or a new product or module as a replacement or spare.

Customers should contact GE if they need further information concerning the level of service that is provided on a per product basis.

For Additional Information

If we can provide assistance with migration to new products, please contact us for help. Advice and assistance are also available via: <http://www.gegridsolutions.com/contact.htm?loc=3> or <http://www.gegridsolutions.com/multilin>