



# DAPmini, DAP-100, DAP-300, DAP-SEL, DAP-UNOP-1618D, DAP-UNOP-1628D, & DAP-UNO-4672 Discontinuance Notice

Excerpt from Publication Number: PRBT-0402

Issued: 4<sup>th</sup> January 2018

Revision Dates:

- 13<sup>th</sup> February 2018
- 20<sup>th</sup> March 2018
- 14<sup>th</sup> December 2025 (Rebranding Revisions)

Copyright © 2025 GE Vernova

## Background

GE Vernova Grid Solutions is committed to customer care and the support of our offerings. As part of this commitment, we strive to design high quality offerings, provide knowledge-based support, and to communicate the availability of new features or offerings as well as the pending discontinuation of manufacturing for older offerings or design variants.

Effective 1<sup>st</sup> January 2018 the manufacturing and supply of DAPmini, DAP-100, DAP-300, DAP-SEL, DAP-UNOP-1618D, DAP-UNOP-1628D, & DAP-UNO-4672 has been discontinued.

On 13<sup>th</sup> February 2018, this notice was revised.

On 20<sup>th</sup> March 2028, the notice was revised to add an appendix.

On 14<sup>th</sup> December 2025, this notice was revised to remove the appendix and revised in accordance with GE Vernova rebranding guidelines.

OFFERING	STATUS	ALTERNATIVE
<b>DAPmini</b> Substation Data Management Unit	<b>Order Book Closed</b>	<b>D20MX</b> Substation Controller
<b>DAP-100</b> Substation Data Management Unit	<b>Order Book Closed</b>	<b>DAP-AT or DAP-416</b> Substation Server
<b>DAP-300</b> Substation Data Management Unit	<b>Order Book Closed</b>	<b>DAP-AT or DAP-416</b> Substation Server
<b>DAP-SEL</b> (SEL 3355 & SEL 3354)	<b>Order Book Closed</b>	<b>DAP-AT or DAP-416</b> Substation Server
<b>DAP-UNOP-1618D</b> 8-Port RS-232/422/485	<b>Order Book Closed</b>	<b>Advantech ECU-1618D</b> 8-Port RS-232/422/485
<b>DAP-UNOP-1628D</b> 8-Port RS-232/422/485	<b>Order Book Closed</b>	<b>Advantech ECU-1628D</b> 8-Port RS-232/422/485
<b>DAP-UNO-4672</b> Substation Server	<b>Order Book Closed</b>	<b>DAP-AT or DAP-416</b> Substation Server

## Support

Continued product support is dependent upon the availability of replacement parts: estimated repair service time frame is 5 years from the initial publication date of this notice. Please see clarifications below.

Returns and repairs will continue to be processed for the following products:

- DAP-UNOP-1618D
- DAP-UNOP-1628D
- DAP-UNO-4672

Returns and repairs will no longer be processed for the following products:

- DAP-mini
- DAP-100
- DAP-300
- DAP-SEL

## For Additional Information

If we can provide assistance with migration to new offerings, please contact us for help. Advice and assistance are also available via: <https://www.gevernova.com/grid-solutions/contact.htm?loc=3> or <https://www.gevernova.com/grid-solutions/automation/protection-control-metering>.