# GE Vernova Grid Solutions

## Reason MU320 Extended

# Software version MU320E Configurator 4.3.0 – Release Notes

Copyright @ 2025 GE Vernova

### **Overview**

GE Vernova regularly introduces software updates to address enhancements in different functional areas. This software release includes the following:

- · Rebranding from GE to GE Vernova.
- Small bug and improvement fixes.

All users are strongly advised to update to this software version.

**Software Release Date: Dec 2025** 

#### **Software Upgrade Process**

Uninstall previous software version and install the version 4.3.0.

#### **HW Compatibility**

This software is compatible to MU320E Hardware Version E.

Please contact your local sales representative or Grid Automation Global Contact Center for any questions regarding this upgrade.

GE Vernova - Grid Solutions

### Release details

In the following release descriptions, a revision category letter is placed to the left of the description. Refer to the Appendix at the end of this document for a description of the categories displayed.

#### **G** Rebranding

Software rebranding from GE to GE Vernova.

#### N Conformal Coating in CORTEC configuration

Include the option to choose conformal coating in CORTEC configuration screen.

#### **E** Characters allowed

Increase number of characters allowed for binary inputs, binary outputs and goose inputs.

#### **G** Small bug fixes

Some small bugs were fixed to improve the software stability.

2 GE Grid Solutions

# **Appendix**

## **Change categories**

This document uses the following categories to classify the changes.

**Table 1: Revision Categories** 

Code	Category	Comments	
N	New feature	A separate feature added to the product. Changes to existing features even if they significantly expand the functionality are not in this category	
G	Change	A neutral change that does not bring any new value and is not correcting any known problem	
E	Enhancement	Modification of an existing feature bringing extra value to the application	
D	Changed, incomplete or false faceplate indications	Changes to, or problems with text messages, LEDs and user push buttons	
R	Changed, incomplete or false product records	Changes to, or problems with product records (syslog, oscillography, demand, fault reports, etc.)	
С	Protocols and communications	Changes to, or problems with protocols or communication features	
В	Unexpected restart	Product restarts unexpectedly	
CS	Cyber security	Cyber security improvements	

## For further assistance

Region	E-mail	Telephone
Global Contact Centre	ga.support@gevernova.com	+44 1785 250070
Central, East Asia, Pacific	ga.supportceap@gevernova.com	+61 414 730 964
India	ga.supportind@gevernova.com	+91 44 2264 8000
Middle East, North Africa, Turkey	ga.supportmenat@gevernova.com	+971 4 375 6950
Europe, Russia, CIS, Sub-Saharan Africa	ga.supportercis@gevernova.com	+34 94 485 8854
North America	ga.supportnam@gevernova.com	+1 877 605 6777
Latin America	ga.supportlam@gevernova.com	+55 48 2108 0300

 $\begin{tabular}{ll} Website: $\underline{$https://www.gevernova.com/grid-solutions/automation/protection-control-metering/merging-units/reason-mu320e} \end{tabular}$ 

GE Vernova - Grid Solutions 3