



Release Notes

Date: **25 September 2025**Distribution: **Public**Reference: **H49-FW-RN-EN-1**

H49 switches Release Notes

References

Publication number	H49-FW-RN-EN-1
Firmware Release	H49-2.1.0
Release date	25 September 2025

Key New Features

- New firmware running on a recent operating system fixing the vulnerabilities of the firmware prior to version 2.1.0

Cybersecurity improvements

- This version provides cybersecurity improvements for the product
- SSH protocol disabled by default
- SNMP is disabled by default. When SNMP is enabled, it will have read-only permissions by default.

Notable bug fixes

- Fixed issue with local time setting on Global Settings page
- Fixed issue with SNMP disabling in Web UI

Hardware compatibility

Compatible with all H49 hardware

Upgrade procedure

To upgrade the H49 product from a release prior to h49-2.1.0, follow the process below:

1. Download the H49 configuration files.
2. Upgrade first to previous firmware release version h49-2.0.3.1, if it is not yet your current version.
3. Upgrade to h49-2.1.0.
4. DO NOT CHECK the option "Check this box if you want to save the configuration before upgrading the firmware."
5. After the firmware upgrade, power off then power on the H49 product.
6. Restore your H49 configuration file.

For Product Support

For questions or further product support, please contact the GE Vernova support team using:

Region	E-mail	Telephone
Global Contact Centre	ga.support@gevernova.com	+44 1785 250070
Central, East Asia, Pacific	ga.supportCEAP@gevernova.com	+61 414 730 964
India	ga.supportIND@gevernova.com	+91 44 2264 8000
Middle East, North Africa, Turkey	ga.supportMENAT@gevernova.com	+971 4 375 6950
Europe, Russia, CIS, Sub-Saharan Africa	ga.supportERCIS@gevernova.com	+34 94 485 8854
North America	ga.supportNAM@gevernova.com	+1 877 605 6777
Latin America	ga.supportLAM@gevernova.com	+55 48 2108 0300

Document revision history

Version	Date	Change Description
H49-FW-RN-EN-1	25 September 2025	Initial release

Disclaimer:

Unless the product is under a GE Vernova service contract, GE Vernova assumes no responsibility or liability for the content of Release Notes or for making Release Notes available to customer.

Performing updates/upgrades to software/firmware is solely the responsibility of the customer.